



F4H-1 STRUCTURE

The enclosed drawings were prepared for the Handbook of Structural Repair Instructions, NAVWEPS 01-245FDA-3, BIS Aircraft Numbers 145311 through 145317 and RCVG Aircraft Numbers 146817 through 146821 and 148252 through 148275. Revisions will be made to include major structural changes in subsequent production aircraft. Corrections may be submitted to W. Holton, Dept. 84.